

Mainline 6B 2012 Maintenance and Rehabilitation & Line 6B Replacement Projects
IDEM Water Quality Certification Independent Environmental Monitor Weekly Observation Report

Observation Dates:	04/28/14 thru 05/03/14
IEM Name:	Eric Sorenson
Waterbody Identification Number(s):	S-486-A, S-487-A, S-489-Z
Wetland Identification Number(s):	W-486-A, W-486-B, W-486-C, W-486-C, W-488-A, W-489-Y, W-489-Z, W-489-C, W-491-B
Enbridge Land Tract Identification Number(s):	N-620-4-1, N-620-4L, N-620-4A, N-620-9, N-621-2C-1, N-621-2C-1, N-621-2B-4, N-622-9, N-622-10A-1, N-623-2, N-625-1
County(s): St. Joseph, LaPorte, Porter	Porter and LaPorte
<p>04/28/14: Pipeline contractor is performing repairs from punch list generated by environmental team. 04/29/14: Pipeline contractor is performing repairs from punch list generated by environmental team. 04/30/14: No contractor activity. 05/01/14: Performed storm water inspections. No issues found. 05/02/14: Performed storm water inspections. No issues found. 05/03/14: No contractor activity.</p>	



sta#1126+00_MP486.5_S-486-A_ECD'S in working order_NW



sta#1160+00_MP487.1_W486-C_ECD'S in working order_W



sta#1165+00_MP487.3_S-487-A_ECD'S in working order_N



sta#1264+00_MP489.2_W489-Y_ECD'S in working order_W



sta#1295+00_MP489.6_W-489-C_ECD'S in working order_W



sta#1394+00_MP491.4_W-491-B_ECD'S in working order



